

## Case Study Tabor Science College (8 Labs)

Strip out existing furniture.  
Patch up flooring (where old service pods were removed).  
1st & 2nd fix M & E installation.  
Manufacture and install new furniture.  
Install Window tints & window blinds to some classrooms.



## case study

